

F-8SDI-B-3G-TX/RX**Quick Setup Guide****Step 1: Connect Power**

1). Connect Included Power Cables to both Transmitter (TX) and Receiver (RX)

2). POWER indicator LEDs on both TX and RX will light when units are powered on

**Step 2: Connect Fiber**


Connect Transmitter to Receiver using Single Mode Fiber with ST/PC connector (Not Included)
Distance up to 20km




FIBER indicator LEDs will light on both TX and RX when fiber is properly connected

Step 3: Connect Inputs/Outputs

Connect SDI inputs and outputs to the corresponding ports of the TX and RX. Once an input is connected, the signal will instantly appear on the corresponding output.



Step 4: Loop Outputs (Example)



V1-V8 LEDs on both TX and RX will light GREEN when INPUT is properly connected

Scan for More:



F-8SDI-B-3G-TX/RX

Quick Setup Guide



<https://thorbroadcast.com>

800-521-8467

sales@thorfiber.com